Syllabus for the trade

of

FITTER

(SEMESTER PATTERN)

Under

CRAFTSMAN TRAINING SCHEME

Designed in 2013

By

Government of India Ministry of Labour & Employment Directorate General of Employment & Training CENTRAL STAFF TRAINING AND RESEARCH INSTITUTE Block - EN - 81 SECTOR – V, SALT LAKE CITY, KOLKATA – 700 091

13.08.2010 at CSTARI, Kolkata				
SL. NO.	NAME AND DESIGNATION	REPRESENTING ORGANIZATION	REMARKS	
	S/SHRI			
1	S.D.Lahiri, Director	C.S.T.A.R.I, Kolkata	Chairman	
2	S. Bhattacharya, Director	W.B.R.E.D.A, Kolkata	Member	
3	Amarnath Sanyal, Addl, Director	I.EM, Kolkata	Member	
4	R. Gangopadhyay, Lecturer	Kanchrapara Railway Workshop, Eastern-Railway	Member	
5	R, N. Banerjee, Director	Sunshine Power Products, Kolkata	Member	
6	P. K. Ghosh, Training Manager	G.R.S.E. Ltd, Kolkata	Member	
7	S. K. Pal, Manager	M/s Mascot Integrated Industry, Kolkata	Member	
8	Dr. Soumen Bose, Dy, Director	Directorate of Industrial Training, WB	Member	
9	Dibyendu Paul, Lecturer	Sahaj Academy, Kolkata	Member	
10	Dr. Tapas Kr Majumder, Manager	B S N L, Kolkata	Member	
11	S.K.Bose, Manager	Trans Bio Energy Ltd, Kolkata	Member	
12	Monisha Sarkar, Asstt Manager	Trans Bio Energy Ltd, Kolkata	Member	
13	Dr.K. mukhopadhya, Director	AGNI, Kolkata	Member	
14	Anupam Bose, Manager	Geetanjali Solar, Kolkata	Member	
15	A Majumder, DE	W.B.R.E.D.A, Kolkata	Member	
16	Joy Chakraborty, DE	W.B.R.E.D.A, Kolkata	Member	
17	Utpal Kr Roy, Supervisor	W.B.R.E.D.A, Kolkata	Member	
18	A.Ghosh, Supervisor	W.B.R.E.D.A, Kolkata	Member	
19	Moloy Kr Mondal, Supervisor	W.B.R.E.D.A, Kolkata	Member	
20	Rudrendu Basu, Asstt. Director	W.B.R.E.D.A, Kolkata	Member	
21	S.K.Biswas, Asstt Director	W.B.R.E.D.A, Kolkata	Member	
22	D.K.Hazra, Spervisor	W.B.R.E.D.A, Kolkata	Member	
23	A.Karmakar, Supervisor	W.B.R.E.D.A, Kolkata	Member	
24	Gautam Banerjee, Manager	ESAB India Ltd, Kolkata	Member	
25	M.K.Saha, Trg Superintendent	G.R.S.E. Ltd. Kolkata	Member	
26	P.Majumder, Chief Consultant	Park Chember Housing Development, Kolkata	Member	
27	Rabin Debnath, Asstt. Director	Directorate of Industrial Training, WB	Member	
28	Sib Chandra Pal, Instructor	Govt, ITI, Howrah Homes, WB	Member	
29	D.P.Sarkar, Instructor	Govt, ITI, Howrah Homes, WB	Member	
30	Anil Kumar, Joint Director of Trg	C.S.T.A.R.I, Kolkata	Member	
31	L. K. Mukherjee, Dy.Director of Trg	C.S.T.A.R.I, Kolkata	Member	
32	A. Nandi, Dy.Director of Trg	C.S.T.A.R.I, Kolkata	Member	
33	N.Nath, Asstt. Director of Trg	C.S.T.A.R.I, Kolkata	Member	
34	P.K.Dutta, Asstt. Director of Trg	C.S.T.A.R.I, Kolkata	Member	
35	S. B. Sarder, Asstt. Director of Trg	C.S.T.A.R.I, Kolkata	Member	
36	R. N. Manna, Trg. Officer	C.S.T.A.R.I, Kolkata	Member	
37	L. M. Pharikhal, Trg-Officer	ATI, Kolkata	Member	

List of members of Trade Committee meeting for the Trade of FITTER Held on 12.08.2010 & 13.08.2010 at CSTARL Kolkata

List of members attended the Workshop to finalize the syllabi of existing CTS into Semester Pattern held from 6th to 10th May'2013 at CSTARI, Kolkata.

Sl. No.	Name & Designation	Organisation	Remarks
1.	R.N. Bandyopadhyaya, Director	CSTARI, Kolkata-91	Chairman
2.	K. L. Kuli, Joint Director of Training	CSTARI, Kolkata-91	Member
3.	K. Srinivasa Rao,	CSTARI, Kolkata-91	Member
	Joint Director of Training		
4.	L.K. Muhkerjee,	CSTARI, Kolkata-91	Member
	Deputy Director of Training		
5.	Ashoke Rarhi,	ATI-EPI, Dehradun	Member
	Deputy Director of Training		
6.	N. Nath,	CSTARI, Kolkata-91	Member
	Assistant Director of Training		
7.	S. Srinivasu,	ATI-EPI, Hyderabad-13	Member
	Assistant Director of Training		
8.	Sharanappa,	ATI-EPI, Hyderabad-13	Member
	Assistant Director of Training		
9.	Ramakrishne Gowda,	FTI, Bangalore	Member
	Assistant Director of Training		
10.	Goutam Das Modak,	RVTI, Kolkata-91	Member
	Assistant Director of Trg./Principal		
11.	Venketesh. Ch., Principal	Govt. ITI, Dollygunj, Andaman &	Member
		Nicobar Island	
12.	A.K. Ghate, Training Officer	ATI, Mumbai	Member
13.	V.B. Zumbre, Training Officer	ATI, Mumbai	Member
14.	P.M. Radhakrishna pillai,	CTI, Chennai-32	Member
	Training Officer		
15.	A.Jayaraman, Training officer	CTI Chennai-32,	Member
16.	S. Bandyopadhyay, Training Officer	ATI, Kanpur	Member
17.	Suriya Kumari .K , Training Officer	RVTI, Kolkata-91	Member
18.	R.K. Bhattacharyya, Training Officer	RVTI, Trivandrum	Member
19.	Vijay Kumar, Training Officer	ATI, Ludhiana	Member
20.	Anil Kumar, Training Officer	ATI, Ludhiana	Member
21.	Sunil M.K. Training Officer	ATI, Kolkata	Member
22.	Devender, Training Officer	ATI, Kolkata	Member
23.	R. N. Manna, Training Officer	CSTARI, Kolkata-91	Member
24.	Mrs. S. Das, Training Officer	CSTARI, Kolkata-91	Member
25.	Jyoti Balwani, Training Officer	RVTI, Kolkata-91	Member
26.	Pragna H. Ravat, Training Officer	RVTI, Kolkata-91	Member
27.	Sarbojit Neogi, Vocational Instructor	RVTI, Kolkata-91	Member
28.	Nilotpal Saha, Vocational Instructor	I.T.I., Berhampore, Murshidabad,	Member
		(W.B.)	
29.	Vijay Kumar, Data Entry Operator	RVTI, Kolkata-91	Member

General Information

1. Name of the Trade	: FITTER
2. N.C.O. Code No.	: 842.10, 842.15
3. Duration	: 2 Years (Four Semesters having duration of six months each)
4. Power norms	: 3.51 KW
5. Space norms	: 88 Sq.m
6. Entry Qualification	: Passed 10th class examination under 10+2 system of education with Science and Mathematics or its equivalent.
7. Unit Size (No. of Student)	: 16
8a. Instructor's/Trainer's Qualificat	ion: Degree in Mechanical Engineering from recognized engineering College /university with one year experience in the relevant field
	OR
	Diploma in Mechanical Engineering from recognized board Of technical education with two years experience in the relevant
	OR
	10 th Class Pass + NTC/NAC in the Trade of "Fitter" With 3 years post qualification experience in the relevant field.
8b. Desirable qualification	: Preference will be given to a candidate with CIC (Craft Instructor

Note: At least one Instructor must have Degree/Diploma in Mechanical Engineering.

Syllabus for the Trade of "Fitter" Under Craftsman Training Scheme

<u>First Semester</u> (Semester Code no. FTR - 01) Duration : Six Month

XX 7 1			г · ·	X 7 (* 1
Week	Trade Practical	Trade Theory	Engineering	Vocational
No.			Drawing	Science and
				Calculation
1.	Familiarization with the	Importance of safety and		
	Institute, Importance of	general precautions observed in		
	trade training, Machinery	the Institute and in the section.		
	used in the trade, types of	Importance of the trade in the		
	work done by the trainees in	development of Industrial		
	the trade. Introduction to	economy of the country. What		
	safety equipments and their	are the related instructions,		
	uses. Introduction of first	subjects to be taught,		
	aid, Road safety, operation	achievement to be made,.		
	of Electrical mains.	recreational, medical		
	Occupational Safety &	facilities and other		
	Health	extracurricular activities of the		
		Institute. (All necessary		
	Basic safety introduction,	guidance to be provided to the		
	Personal protection:-	new comers to become familiar		
	Basic injury prevention,	with the working of Industrial		
	Basic first aid, Hazard	Training Institute system		
	identification and	including stores procedures.		
		Introduction of First aid. Road		
	avoidance, safety signs	safety. Operation of electrical		
	for Danger, Warning,	mains. Introduction of safety		
	caution & personal safety	kits. Presentation by CD or		
	message.	DVD of safety to the newly		
	Use of Fire extinguishers.	admitted trainees so that they		
	Visit & observation of	can know reason of accidents.		
	sections.	can know reason of accidents.		
2.	Marking out lines, gripping	Safety, accident prevention,	Engineering	Introduction to
	suitably in vice jaws,	linear measurements- its units,	Drawing	Property and uses
	hacksawing to given	dividers, calipers,	introduction to	of C.I. and
	dimensions, sawing different	hermaphrodite, centre punch,	Engg. Drawing,, its	wrought Iron.
	types of metals of different	dot punch, their description and	importance.	
	sections.	uses of different types of	mipor turico.	
	50010115.	hammers. Description, use and		
		care of 'V' Blocks, marking off		
		table.		
3.	Filing Channel Derellal		Types of lines their	Arithmetic:
3.	Filing Channel, Parallel.	Bench vice construction, types,	Types of lines their	
	Filing- Flat and square	uses, care & maintenance, vice	meaning &	Fundamental
	(Rough finish).	clamps, hacksaw frames and	application as per	operations,-
		blades, specification,	BIS 696	addition,
		description, types and their		subtraction.

		uses, method of using hacksaws.		multiplication, division of decimal number
4.	Filing practice, surface filing, marking of straight and parallel lines with odd leg calipers and steel rule, marking practice with dividers, odd leg calipers and steel rule (circles, arcs, parallel lines).	Files- specifications, description, materials, grades, cuts, file elements, uses. Measuring standards (English, Metric Units), angular measurements, subdivisions, try square, ordinary depth gauge, protractor- description, uses and cares.	Simple conventional symbols for material and parts as per BIS696	Properties and uses of plain carbon steel and alloy steel.
5.	Marking off straight lines and arcs using scribing block and dividers, chipping flat surfaces along a marked line.	Marking off and layout tools, dividers, scribing block, odd leg calipers, punches- description, classification, material, care & maintenance.	Use of drawing instruments in the construction of Geometrical drawings- angles, triangles.	Fraction and decimal - conversion fraction decimal and vice-versa.
6.	Marking, filing, filing square, use of tri-square.	Calipers- types, material, constructional details, uses, care & maintenance of cold chisels- materials, types, cutting angles.	Geometrical construction of rectangles, square, circles.	Properties and uses of copper, zinc, lead, tin, aluminum.
7&8	Marking according to simple blue prints for locating, position of holes, scribing lines on chalked surfaces with marking tools, finding center of round bar with the help of 'V' block and marking block. Joining straight line to an arc.	Marking media, marking blue, Prussian blue, red lead, chalk and their special application, description. Use, care and maintenance of scribing block.	Geometrical construction of polygon and ellipse, parabola & hyperbola.	Composition, properties and uses of brass, bronze, solder, bearing material, timber, rubber etc.
9.	Chipping, Chip slots & oils grooves (Straight). Filing flat, square, and parallel to an accuracy of 0.5mm. Chip curve along a line-mark out, key ways at various angles & cut key ways.	Surface plate and auxiliary marking equipment, 'V' block, angle plates, parallel block, description, types and uses, workshop surface plate- their uses, accuracy, care and maintenance. Types of files- convexing, taper, needle, care and maintenance of files, various types of keys, allowable clearances & tapers, types, uses of key pullers.	Geometrical construction of involutes, oval, and helix.	area, volume capacity, weight, time, angle, their conversions. Effect of alloying elements in the properties of C.I. & steel.
10.	File thin metal to an accuracy of 0.5 mm. Chip & chamfer, grooving and slotting	Physical properties of engineering metal: colour, weight, structure, and conductivity, magnetic, fusibility, specific gravity. Mechanical properties: ductility, malleability hardness,	Free hand sketching of straight lines, rectangles, circles, square, polygons, ellipse.	Unit of temperature for & related problems. Standard & absolute temp.

		brittleness, toughness, tenacity, and elasticity.		
11.	Saw along a straight line, curved line, on different sections of metal. Straight saw on thick section, M.S. angle and pipes.	Drilling processes: common type (bench type, pillar type, radial type), gang and multiple drilling machine.	Free hand sketching of straight lines, rectangles, circles, square, polygons, ellipse.	Mass, volume, density, sp. Gravity & specific weight S.I. M.K.S. and F.P.S. units of force, weight etc. their conversion to related problems.
12.	File steps and finish with smooth file accuracy \pm 0.25 mm. File and saw on M.S. Square and pipe welds	Micrometer- outside and inside – principle, constructional features, parts graduation, leading, use and care. Micrometer depth gauge, parts, graduation, leading, use and care. Digital micrometer.	Standard printing style for letters and numbers as per IS : 696.	Mass, volume, density, weight, S.I., M.K.S. and F.P.S. units of force weight etc. their conversion to related problems.
13.	File radius along a marked line (Convex & concave) & match. Chip sheet metal (shearing). Chip step and file.	Vernier calipers, principle, construction, graduations, reading, use and care. Vernier bevel protractor, construction, graduations, reading, use and care, dial Vernier Caliper, Digital vernier caliper.	Free hand sketching of simple geometrical solids, cube, cone, prism, cylinder, sphere, pyramids.	Inertia, rest and motion, velocity and acceleration.
14.	Punch letter and number (letter punch and number punch), use of different punches.	Drill holding devices- material, construction and their uses.	Scales- construction plan, Representing fraction	Concept of scalar and vector quantity with examples, Newton's Law of motion.
15.	Prepare forge. Fire for heating metals. Forge a square rod from round stock. Judge the forging temperature of various metals.	Safety precautions to be observed in a smith shop, forge - necessity, description uses, fuel used for heating, bellows blowers, description and uses.	Construction of diagonal scale.	Power and roots Factor, Power base exponents number.
16.	Forge M.S. bar to square, octagon and hexagon.	Anvil and swage blocks. Description and uses. Forging tools- hammers- band and sledge, description and uses. Chisels, set hammers, flatters, hardier, fuller swage & uses.	Simple dimensioning technique, size and location, dimensions of parts, holes angles, taper, screw etc. as per BIS. 696.	Multiplication and division of power and root of a number.
17.	Forge flat chisel, grind.	Measuring and checking tools- steel rule, brass rule, calipers, try square, description and uses. General idea about the main operations performed in a forging shop such as upsetting drawing, twisting, bending, punching, drilling, and	Transferring measurements for linear, angular, circular dimensions form the given object to the related free hand sketches using different	Square root of number and problems

		welding.	measuring instruments.	
18.	Forge – punches, screw drivers, chisels, grind them to shape and heat treat to requirement, bending metals to angles, curves & twisting, Preparation of brackets.	Heat treatment, various heat treatment methods - normalizing, annealing, hardening and tempering. Power hammer – construction, features, method of operating and uses.	Pictorial drawings, isometric drawings of simple geometrical solids.	Work energy and power, their units and applied problems.
19.	Marking of straight lines, circles, profiles and various geometrical shapes and cutting the sheets with snips. Marking out of simple development, marking out for flaps for soldering and sweating.	Safety precautions to be observed in a sheet metal workshop, sheet and sizes, Commercial sizes and various types of metal sheets, coated sheets and their uses as per BIS specifications.	do	do
20	Make various joints: wiring, hemming, soldering and brazing, form locked, grooved and knocked up single hem straight and curved edges form double hemming,. Punch holes- using hollow and solid punches. Do lap and butt joints.	Marking and measuring tools, wing compass, Prick punch, tin man's square tools, snips, types and uses. Tin man's hammers and mallets type-sheet metal tools, stakes-bench types, parts, their uses. Soldering iron, types, specifications, uses. Trammel- description, parts, uses. Hand grooves- specifications and uses.	Oblique projection of simple geometrical solids.	Percentage, changing percentage to decimal and fraction and vice versa. Applied problems.
21.	Bend sheet metal into various curvature form, wired edges- straight and curves, fold sheet metal at angle using stakes. Bend sheet metal to various curvatures. Make simple Square, container with wired edge and fix handle.	Solders-composition of various types of solders, and their heating media of soldering iron, fluxes types, selection and application-joints wiring- various types of metal joints, their selection and application, tolerance for various joints, their selection & application.	Oblique projection of simple geometrical solids.	Problem on percentage related to trade.
22.	Make square tray with square soldered corner Make funnel as per development and solder joints Make riveted lap and butt joint. Welding - Striking and maintaining arc, laying straight-line bead.	Rivets-Tin man's rivets, types, sizes, selection for various works. Riveting tools, dolly snaps, description and uses. Method of riveting, shearing machine- description, parts and uses. Safety-importance of safety and general precautions observed in a welding shop. Precautions in electric and gas welding. (Before, during, after) Introduction to safety equipment and their uses.	Isometric drawing of simple machined & casting blocks.	Different types of loads, stress, strain, modulus of elasticity. Ultimate strength, different types of stress, factor of safety, examples.

23-	Making square, butt joint	Hand tools: Hammers, welding	do	do
24.	and 'T' fillet joint-gas and arc. Do setting up of flames, fusion runs with and without filler rod, gas and arc. Make butt weld and corner, fillet welding- Gas and Arc. Practice in soft soldering and silver soldering. Gas cutting.	description, types and uses, Machines and accessories, welding transformer, welding generators, description, principle, method of operating, carbon dioxide welding. H.P. welding equipment: description, principle, method of operating L.P. welding equipment: description, principle, method of operating. Types of Joints-Butt and fillet as per BIS specifications. Oxygen acetylene cutting- machine description, parts, uses, method of handling, cutting torch-description, parts, function and uses. Gases and gas cylinder description, kinds, main difference and uses.	Free hand sketches of trade related hand tools and measuring tools.	Ratio & proportion- Ratio, finding forms ratio proportions, direct proportion and indirect proportion. Application of ratio and proportion & related problems.
25.		Project Work / Industrial Visit	(Optional)	<u> </u>
26.		Examination		

Syllabus for the Trade of "Fitter" Second Semester (Semester Code no. FTR - 02) Duration : Six Month

Sl.No.	Trade Practical	Trade Theory	Engineering Drawing	Vocational Science and Calculation
1	True job on four jaw chuck using knife tool, face both the ends for holding between centers, Using roughing tool parallel turn \pm 0.1 mm. Measure the diameter using outside caliper and steel rule.	Safely precautions to be observed while working on a lathe, Lathe specifications, and constructional features. Lathe main parts descriptions- bed, head stock, carriage, tail stock, feeding and thread cutting mechanisms. Holding of job between centers, works with catch plate, dog, simple description of a facing and roughing tool and their applications.	Simple sketches of trade related hand tools & measuring instruments	Simple machines- principle, velocity ratio, mechanical advantage, efficiency, related problems.
2	Lathe operations- the facing, parting and form tools, plain turn, step turn, holding job in three jaw chuck- deburr, chamfer- corner, round, the ends, Shoulder turn : square, filleted, beveled under cut shoulder, turning-filleted under cut, square beveled.	Lathe cutting tools- Brief study of the nomenclature of Lathe cutting tools and necessity of correct grinding, solid and tipped, throw away type tools, cutting speed and feed and comparison for H.S.S., carbide tools. Use of coolants and lubricants.	Machines- basic principles, velocity, ratio, mechanical advantage, and efficient, simple problems.	Simple machines- principle, velocity ratio, mechanical advantage, efficiency. Simple problems.
3	Cut grooves- square, round 'V' groove, Make a mandrel-turn diameter to sizes. Knurl the job.	Chucks and chucking the independent four-jaw chuck. Reversible features of jaws, the back plate, Method of clearing the thread of the chuck- mounting and dismounting, chucks, chucking true, face plate, drilling - method of holding drills in the tail stock, Boring tools and enlargement of holes.	Orthographic drawings, application of both the first angle and third angle. Method of representing the drawings for simple and complex machine parts, exercises with dimensions.	Algebraic symbols, fundamental algebra operations, sign and symbols used in algebra, coefficient terms, and unlike terms.

4	Bore holes –spot face, pilot drill, enlarge hole, using boring tools, make a bush step bore-cut recess, turn hole diameter to sizes.	General turning operations- parallel or straight, turning. Stepped turning, grooving, shape of tools for the above operations. Appropriate method of holding the tool on tool post or tool rest, Knurling: - tools description, grade, uses, speed and feed, coolant for knurling, speed, feed calculation.	do	Algebraic addition, sub traction, multiplication and division.
5	Turn taper (internal and external). Turn taper pins. Turn standard tapers to suit with gauge.	Taper – definition, use and method of expressing tapers. Standard tapers- taper, calculations Morse taper.	Orthographic drawings application of both the first angle and third angle. Method of representing the drawings for simple and complex machine blocks given for exercises with dimensions.	Power and exponent. Laws of exponent.
6	Threading practice by using cut threads using taps, dies on lathe by hand, 'V' thread – external. Prepare a nut and match with the bolt.	Screw thread definition – uses and application. Terminology of screw threads, square, worm, buttress, acme (non standard-screw threads),Principle of cutting screw thread in centre lathe –principle of chasing the screw thread – use of centre gauge, setting tool for cutting internal and external threads, use of screw pitch gauge for checking the screw thread.	do	Algebraic simplification problems.
7	Mark off and drill through holes, drill on M.S. flat, file radius and profile to suit gauge.	Drill- material, types, (Taper shank, straight shank) parts and sizes. Drill angle-cutting angle for different materials, cutting speed feed.	Standard method of sectioning as per B IS: 696. Exercises for different sectional views on the given	Simple machines like winch pulley and compounding axle etc.

		R.P.M. for different materials.	orthographic drawing of machine part, castings etc	
8	Step fit, angular fit, file and make angle, surfaces (Bevel gauge accuracy 1 degree) make simple open and sliding fits.	Drill troubles: causes and remedy. Equality of lips, correct clearance, dead centre, length of lips. Drill kinds : Fraction, metric, letters and numbers, grinding of drill.	do	Factors and equations: Algebraic formula.
9	Enlarge hole and increase internal dia. File cylindrical surfaces. Make open fitting of curved profiles.	Grinding wheel: Abrasive, grade structures, bond, specification, use, mounting and dressing. Bench grinder parts and use-radius gauge, fillet gauge, material, construction, parts function and metric, different dimensions, convex and concave uses care and maintenance.	Do	Factors and different types of factorisation.
10	Make the circles by binding previously drilled hole. Test angular match up.	Radius gauge, feeler gauge, hole gauge, and their uses.	Standard method of sectioning as per BIS.696 Exercises for different sectional views on the given orthographic drawing of machine parts, casting etc	Equations simple simultaneous equation
11-12	Inside square fit, make combined open and sliding fit, straight sides 'T' fit.	Vernier height gauge : material construction, parts, graduations (English & Metric) uses, care and maintenance, Pig Iron : manufacturing process (by using)Blast furnace types, of pig Iron , properties and uses.	Conversion of isometric, oblique drawings to orthographic drawings and vice- versa. Related problems such as 'V' block oriented by various machining operations etc.	Equation simple simultaneous, quadratic.

13	File fit- combined, open angular and sliding sides. File internal angles 30 minutes accuracy open, angular fit.	Cast Iron: manufacturing process by using (cupola furnace) types, properties and uses. Wrought iron- : manufacturing process (Fuddling and Astor process) properties and uses.	do	Application, construction and solution of problems by equation.
14	Make sliding fit with angles other than 90°, sliding fit with an angle.	Steel: manufacturing process plain carbon steels, types, properties and uses.	do	Atmospheric pressure, pressure gauge, gauge pressure and absolute pressure and their units.
15	Make simple bracket by bending and twisting of non-ferrous metal. Drill small holes (2mm) Drill holes on sheet metal, bend short for round bracket.	Non-ferrous metals (copper, aluminum, tin, lead, zinc) properties and uses.	do	Logarithms and use of logarithms tables:
16	Form internal threads with taps to standard size (through holes and blind holes) – Drill through hole and tap drill blind hole and tap, prepare studs and bolt.	Screw threads: terminology, parts, types and their uses. Screw pitch gauge: material parts and uses. Taps British standard (B.S.W., B.S.F., B.A. & B.S.P.) and metric /BIS (course and fine) material, parts (shank body, flute, cutting edge). Method of using and use of calculating tap hole sizes. Tap wrench: material, parts, types (solid & adjustable types) and their uses removal of broken tap, studs (tap stud extractor).	do	Logarithms: logarithm and exponent. Use of logarithms and anti-logarithm table.
17	Form external threads with dies to standard size. Prepare nuts and match with bolts.	Dies : British standard, metric and BIS standard, material, parts, types, Method of using dies. Die stock: material, parts and uses.		Arithmetical operations involving logarithms in the computations.

18	Counter sink, counter	Counter sink, counter		Problem related to
10	bore and ream split fit	bore and spot facing-tools		the trade using
	(three piece fitting).	and nomenclature,	do	logarithm tables.
	(timee piece inting).	Reamer- material, types		loguinin tuolos.
		(Hand and machine		
		reamer), kinds, parts and		
		their uses, determining		
		hole size (or reaming),		
		Reaming procedure.		
19	Filling & scraping of	Scrapers and their types,	do	do
17	bearing to close precision.	methods of scraping.	do	uo
20	File and fit combined	Vernier micrometer,	Surface	Specific gravity,
20	radius and angular surface	material, parts,	development of	principle of
	(accuracy ± 0.5 mm),	graduation, use, care and	simple geometrical	Archimedes.
	angular and radius fit.	maintenance.	solids like cube,	Archinicues.
	Locate accurate holes.		rectangular block,	
	Make accurate hole for		cone, pyramid,	
	stud fit.		cylinder, prism	
	stud III.		etc.	
21	Make assembly for	Screw thread micrometer:	do	Relation between
21	dovetail sliding fits using	Construction, graduation	uo	specific gravity
	lower pins and screws	and use.		and density simple
	$(\pm 0.04 \text{ mm})$	and use.		experimental
	(± 0.04 mm)			determination.
22	Cutting threads using	Dial test indicator,		Geometry:
	dies. Make sliding fits	construction, parts,		Fundamental
	assembly with parallel	material, graduation,		geometrical
	and angular mating	Method of use,. Care and	do	definition- angles
	surface. (± 0.04 mm)	maintenance. Digital dial		and properties of
		indicator. Comparators-		angles, triangles,
		measurement of quality in		and properties of
		the cylinder bores.		triangles.
23 &	Simple repair work,	Preventive maintenance-	Interpretation of	Pythagoras
24	simple assembly of	objective and function of	solids and	theorem,
	machine parts from blue	P.M., section inspection.	conventional	properties of
	prints	Visual and detailed,	application of	similar triangles.
	r	lubrication survey, system	intersectional	Revision.
		of symbol and colour	curves on drawing.	
		coding. Revision, simple	Solution of NCVT	
		estimation of materials,	test paper	
		use of handbooks and	(preliminary)	
		reference table.	Revision.	
25		Project Work / Industrial		1
26		Examination		

Syllabus for the Trade of "Fitter" <u>Third Semester</u> (Semester Code no. FTR - 03) <u>Duration : Six Month</u>

Week No.	Trade Practical	Trade Theory	Engineering. Drawing	Vocational Cal. & Science
01	Prepare triangle, hexagon on ends of a cylinder bar, prepare female end and fit.	Keys and keyways. Types and their uses, construction (shape).	Revision of first year topics.	Revision of 1 st year course.
02	Make key and keyways on the shaft and fit. "V" grooves and slots on the cast iron block.	Spring-material types and uses.	do	do
03	Make riveted joints (lap and butt joints)	Bolts and Nuts: Material, types (Hexagonal and square head) and their uses.	Screw thread, their standard forms as per BIS, external and internal thread, conventions on the features for drawing as per BIS.	Rectangle, square, Rhombus, parallelogram and their properties.
04	Drill on cylindrical surface.	Washers: Material, types (spring, tab, plain washer and fiber washer).	do	Circle and properties circle: regular polygons.
05	Scrap on flat surfaces, scrap on curved surfaces and scrap surface parallels and test. Make & assemble, sliding flats, plain surfaces.	Simple scraper- cir., flat, half round, triangular and hook scraper and their uses.	Sketches for bolts, nuts, screws and other screwed members.	Application of geometrical to shop problems.
06	Make simple dowel pins, fitting dowel pins and tap screw assembly.	Dowel pins : material, construction, types ,accuracy and uses.	Sketches for bolts, nuts, screws and other screwed members.	Heat & temperature thermometric scales, their conversions.
07	Assembly sliding for using keys and dowel pin and screw, ± 0.02 mm accuracy on plain surface.	Screws: material, different types (inch & metric), uses	Standard rivet forms as per BIS.	Temperature measuring instruments.
08	Testing of sliding fitting job, scrap on two flat surfaces and curved surfaces.	Testing scraped surfaces: ordinary surfaces without a master plate.	do—	Specific heats of solids & liquids., quantity of heat.
09	File & fit angular mating surface plain	Special files: types (pillar, Dread naught, Barrow,	Riveted joint.	Heat loss and heat gain, with simple

	within an accuracy of ± 0.02 mm & angular 15 minutes angular fitting.	warding) description.		problems.
10	Drill through and blind holes at an angle-drill blind holes, 'Y' fitting.	System of drill size, Fractional size: number, letter and metric. Templates and gauges- Introduction, necessity, types.	Riveted joints- butt.	Mensuration: Plain figures-triangles, square, rectangle, parallelogram.
11	Dovetailed fitting, radius fitting.	Gauges: Introduction, necessity, types- description and uses of gauge- types (feeler, screw, pitch, radius, wire gauge),description and use.	Sketches of keys, cotter and pin joints.	Plain figures. Trapezium, regular polygons, circle, hollow circles.
12	Precision drilling, reaming and tapping. Test- Job.	Limit gauge: Ring gauge, snap gauge, plug gauge, description and uses.	do	Plain figures- segment and sector of circle, ellipse, fillets.
13	File and fit, combined fit with straight, angular surface with ± 0.02 mm accuracy, hexagonal fitting.	Slip gauge: Necessity of using, classification & accuracy, set of blocks (English and Metric). Details of slip gauge. Metric sets 46: 103: 112. Wringing and building up of slip gauge and care and maintenance. Application of slip gauges for measuring, Sine bar- Principle, application & specification.	Sketches for simple pipe, unions with simple pipe line drawings.	Solid figures: Prism, cylinder, pyramid, cone.
14	Drilling and reaming, small dia. holes to accuracy correct location for fitting Make male and female fitting parts, drill and ream holes not less than 12.7 mm.	Locking device: Nuts- types (lock nut castle nut, slotted nuts, swam nut, grooved nut) Description and use.	do	Solid figures: frustum of a cone, sphere, spherical segment.
15	Sliding fitting, Diamond fitting, Lapping flat surfaces using lapping plate.	Lapping: Application of lapping, material for lapping tools, lapping abrasives, charging of lapping tool. Surface	Concept of preparation of assembly drawing and detailing. Simple assemblies	Material weight and cost problems related to trade.

		finish importance, equipment for testing- terms relation to surface finish. Equipment for tasting surfaces quality – dimensional tolerances of surface finish.	& their details of trade related tools/job/exercises with the dimensions from the given sample or models. Tool post for the lathe with washer and screw.	
16	Stepped keyed fitting- test job. Lapping holes and cylindrical surfaces.	Honing: Application of honing, material for honing, tools shapes, grades, honing abrasives. Frosting- its aim and the methods of performance.	do	Trigonometry: trigonometric ratios, use of trigonometric table.
17	Making a snap gauge for checking a dia of 10 ± 0.02 mm.	Interchangeability: Necessity in Engg, field definition, BIS. Definition, types of limit, terminology of limits and fits-basic size, actual size, deviation, high and low limit, zero line, tolerance zone.	Details and assembly of Vee- blocks with clamps.	Area of triangle by trigonometry.
18	Scrape angular mating surface, scrap on internal surface.	Different standard systems of fits and limits. British standard system, BIS system., Method of expressing tolerance as per BIS	Details and assembly of Vee- blocks with clamps.	Finding height and distance by trigonometry.
19	Practice in dovetail fitting assembly and dowel pins and cap screws assembly.	Fits : Definition, types description of each with sketch.	Details of assembly of shaft and pulley.	Application of trigonometry in shop problems.
20	Preparation of gap gauges.	Manufacture: The name and types of gauge commonly used in gauging finished product- Method of selective assembly 'Go' system of gauges, hole plug basis of standardization.	Details of assembly of shaft and pulley.	Application of trigonometry in shop problems
21	Dovetail and Dowel pin assembly, scraps cylindrical bore.	Bearing-Introduction, classification (Journal and Thrust), Description of each, ball bearing: Single	Details of assembly of bush bearing.	Triangle of forces, parallelogram of forces.

		row, double row, description of each, and advantages of double row.		
22	Scrapping cylindrical bore and to make a fit- make a cotter jib assembly.	Roller and needle bearings: Types of roller bearing. Description & use of each. Method of fitting ball and roller bearings.	Details of assembly bush bearing.	Composition and resolution of forces.
23	Scrapping cylindrical taper bore, check taper angle with sine bar, check in per angle (flat) with sine bar.	Bearing metals – types, composition and uses, lubricants purpose of using different types, description and uses of each type.	Details of assembly of a simple coupling.	Representation of forces by vectors- simple problems on lifting tackles like jib cranes, wall cranes etc.
24	Preparation of centre, squares, drills gauges. File and fit straight and angular surfaces internally. Continuation of Filling exercises. Identify different ferrous metals by spark test.	Synthetic materials for bearing: The plastic laminate materials, their properties and uses in bearings. Hardening and tempering, purpose of each method, tempering colour chart. Annealing and normalizing, purpose of each method.	do Details and assembly of a simple hand vice.	do Moments of force, couples. Simple problems on straight and bell cranked lever.
25		Project Work / Industrial	Visit (Optional)	1
26		Examination	1	

Syllabus for the Trade of "Fitter" Fourth Semester (Semester Code no. FTR - 04) Duration : Six Month

Week No.	Trade Practical	Trade Theory	Engineering drawing	Vocational science & calculation
01.	'H' fitting-	Case hardening and carburizing and its methods, process of carburizing (solid, liquid and gas).	Details and assembly of simple hand – vice.	Centre of gravity, simple experimental determination, stable, unstable & neutral equilibrium, simple explanation
02.	Exercises on lapping of gauges (hand lapping only)	Solder and soldering: Introduction-types of solder and flux. Method of soldering, Hard solder- Introduction, types and method of brazing.	do	do
03.	Hand reams and fit taper pin, drilling and reaming holes in correct location, fitting dowel pins, stud, and bolts.	Production of gauges, templates and jigs. The objective of importance for preparing interchangeable components.	do	Friction- co- efficient of friction.
04.	Simple jigs and fixtures for drilling.	Drilling jig-constructional features, types and uses.	Blue print Reading. Simple exercises related to missing lines.	Simple problem related to friction.
05.	Prepare a 'V' block and a clamp.	Fixtures-Constructional features, types and uses.	do	Magnetic substances- natural and artificial magnets.
06	Marking out as per Blue print, drilling, straight and curve filing. Threading with die, cutting slot, and cutting internal threads with taps, making an adjustable spanner.	Revision.	do	Method of magnetisation. Use of magnets.
07.	Flaring of pipes and pipe joints,	Pipes and pipe fitting- commonly used pipes. Pipe	do	Electricity & its uses electric

	Cutting & Threading of pipe length. Fitting of pipes as per sketch. Conditions used for pipe work to be followed. Bending of pipes- cold and hot.	bending methods. Use of bending fixture, pipe threads- Std. Pipe threads Die and Tap, pipe vices.		current-positive & negative terminals.
08.	Practice-dismantling & assembling – globe valves sluice valves, stop cocks, seat valves and non-return valve, fitting of pipes and testing for leakage.	Standard pipefitting Methods of fitting or replacing the above fitting, repairs and erection on rainwater drainage pipes and house hold taps and pipe work. Use of tools such as pipe cutters, pipe wrenches, pipe dies, and tap, pipe bending machine etc.	Simple exercises relating missing symbols.	Use of fuses and switches, conductors and insulators.
09.	Practice in handling Fire extinguishers of different types, refilling of extinguishers.		Simple exercises relating to missing symbols.	Simple electric circuits ,simple calculations.
10.	Marking detail includes male & female screw cutting, male and female fitting parts. Making and tempering springs.	Working material with finished surface as aluminium, duralumin, stainless steel, the importance of keeping the work free from rust and corrosion. The various coatings used to protect metals, protection coat by heat and electrical deposit treatments. Treatments and provide a pleasing finish as chromium silver plating and nickel plating, and galvanizing.	Simple exercises related to missing section.	Ohm's Law. Simple calculation, electrical insulating materials.
11.	Exercises on finished material as aluminium and stainless steel, marking out, cutting to size, drilling etc. without damage to surface of finished articles.	Aluminium and its alloys. Uses ,advantages and disadvantages, weight and strength as compared with steel.	Simple exercises related to missing section.	Graphs : abscissa and ordinates, graphs of straight line, related to two sets of varying quantities.
12.	Making out for angular outlines, filing and fitting the inserts into gaps. Making a simple drilling jig, Marking out, filing to line, drilling and tapping brass and copper jobs.	Tapers on keys and cotters permissible by various standards. Discuss non-ferrous metals as brass, phosphor bronze, gunmetal, copper, aluminium etc. Their composition and purposes where and why used, advantages for	Simple exercises related to missing dimensions.	do

		specific purposes, surface wearing properties of bronze and brass.		
13.	Complete exercises covering the assembly of parts working to detail and arrangement – Drawings. Dismantling and mounting of pulleys. Making replacing damaged keys. Repairing damaged gears and mounting. Repair & replacement of belts.	Power transmission elements. The object of belts, their sizes and specifications, materials of which the belts are made, selection of the type of belts with the consideration of weather, load and tension methods of joining leather belts. Vee belts and their advantages and disadvantages, Use of commercial belts, dressing and resin creep and slipping, calculation.	do	Practice on simple pocket calculator.
14.	Complete exercises covering the assembly of parts working to details and arrangements as per drawings. Dismantling and mounting of pulleys. Making, replacing damaged keys. Repairing damaged gears and mounting them on shafts.	Power transmissions, coupling types-flange coupling,-Hooks coupling-universal coupling and their different uses.	Further practice on logarithm.	Mechanical properties of metals.
15.	More difficult work in marking out including tangents, templates involving use of vernier protractor.	Pulleys-types-solid, split and 'V' belt pulleys, standard calculation for determining size crowning of faces-loose and fast pulleys- jockey pulley. Types of drives- open and cross belt drives. The geometrical explanation of the belt drivers at an angle.	do	do
16.	Fitting of dovetail slides.	Power transmission –by gears, most common form spur gear, set names of some essential parts of the set-The pitch circles, Diametral pitch, velocity ratio of a gear set, Helical gear, herring bone gears, bevel gearing, spiral bevel gearing, hypoid gearing,	Solution of NCVT test.	Basic Electronics.

17.	Male and female dovetail fitting repairs	pinion and rack, worm gearing, velocity ration of worm gearing. Repair to gear teeth by building up and dovetail method. Method or fixing geared wheels for various purpose drives.	Solution of NCVT test	do
	to geared teeth. Repair of broken gear tooth by stud. Repair broker gear teeth by dovetail.	General cause of the wear and tear of the toothed wheels and their remedies, method of fitting spiral gears, helical gears, bevel gears, worm and worm wheels in relation to required drive. Care and maintenance of gears.	papers.	
18.	Marking out on the round sections for geometrical shaped fittings. Finishing and fitting to size, checking up the faces for universality.	Lubrication and lubricants- Method of lubrication. A good lubricant, viscosity of the lubricant, Main property of lubricant. How a film of oil is formed in journal. Bearings, method of lubrication-gravity feed, force (pressure) feed, splash lubrication. Cutting lubricants and coolants: Soluble off soaps, suds-paraffin, soda water, common lubricating oils and their commercial names, selection of lubricants.	do	Transmission of power by belt, pulleys & gear drive. Calculation of Transmission of power by belt pulley and gear drive.
19 & 20	Making-parallel block & 'V' block. Drilling for riveting. Riveting with as many types of rivet as available, use of counter sunk head rivets, use of counter bore tool to fit cheese head bolts. Use of pop rivets and gun.	Chains, wire ropes and clutches for power transmission. Their types and brief description. Discuss the various rivets shape and form of heads, riveting tools for drawing up the importance of correct head size. The spacing of rivets. Flash riveting, use of correct tools, compare hot and cold riveting.	do	Solution of NCVT test papers.
21 & 22	Inspection of Machine tools. Accuracy testing of Machine tools.	Installation, maintenance and overhaul of machinery and engineering equipment and Hydraulics & pneumatic symbols & exercise. Hydraulics pneumatic circuits. Clutch: Type, positive clutch (straight tooth type, angular tooth type).	do	Basic Electronic control system.

23.	Study of power	Washers-Types and calculation	Solution of	Basic Electronic
	transmission system in	of washer sizes. The making of	NCVT test	control system.
	machine tools.	joints and fitting packing. The	papers.	
		use of lifting appliances,		
		extractor presses and their use.		
		Practical method of obtaining		
		mechanical advantage. The		
		slings and handling of heavy		
		machinery, special precautions		
		in the removal and replacement		
		of heavy parts.		
24.	Simple repair of	Foundation bolt: types (rag,		
	machinery, making of	Lewis cotter bolt) description of	do	do
	packing gaskets, use of	each erection tools, pulley block,		
	hollow punches,	crow bar, spirit level, Plumb		
	extractor, drifts,	bob, pipe 2 X 4', wire rope,		
	various types of	manila rope, wooden block.		
	hammers and spanners,			
	etc. Practicing,			
	making various knots,			
	correct loading of			
	slings, correct and safe			
	removal of parts. Erect			
	sample machines.			
25.		Revision		
26.		Examination		

<u>List of Tools & Equipments for the Trade of "Fitter"</u> <u>For 16 trainees + one (for Instructor)</u>

A : Trainees kit

Sl. No.	Name of the items	Qty
1	Steel Rule 15 cm with metric graduation	17 nos.
2	Try Square 10 cm blade.	17 nos.
3	Caliper inside 15 cm spring.	17 nos.
4	Caliper 15 cm hermaphrodite	17 nos.
5	Caliper outside 15 cm spring	17 nos.
6	Divider 15 cm spring	17 nos.
7	Straight Scriber 15 cm.	17 nos.
8	Centre Punch 10 cm	17 nos.
9	Screw driver 15 cm	17 nos.
10	Chisel cold flat 10 cm	17 nos.
11	Hammer ball peen 0.45 kg. With handle	17 nos.
12	Hammer ball peen 0.22 kg. With handle.	17 nos.
13	File flat 25 cm. second cut	17 nos.
14	File flat 25 cm. smooth	17 nos.
15	File half round second cut 15 cm.	17 nos.
16	Hacksaw frame fixed 30 cm.	17 nos.
17	Safety goggles.	17 nos.
18	Dot slot punch 10 cm.	17 nos.

B: Instruments & General Shop Outfit

Sl. No.	Name of the items	Qty
19	Steel Rule 30 cm	4 nos.
20	Steel Rule 60 cm.	4 nos.
21	Straight edge 45 cm steel	2 nos.
22	Surface plate 45 x 45 cm CI / Granite.	2 nos.
23	Marking table 91 x 91 x 122 cm.	1 no.
24	Universal scribing block 22 cm.	2 nos.
25	V-Block pair 7 cm and 15 cm with clamps	2 nos.
26	Square adjustable 15 cm blade.	2 nos.
27	Angle plate 10 x 20 cm.	2 nos.
28	Spirit Level 15 cm metal	1 no.
29	Punch letter 3 mm set.	1 no.
30	Punch number set 3 mm.	1 no.
31	Punch hollow 6 mm to 19 set of 5	2 nos.
32	Punch round 3mm x 4 mm set of 2	2 nos.
33	Portable hand drill (Electric) 0 to 6 mm	2 nos.
34	Drill twist straight shank 1.5 to 12 mm by 0.5 mm	1 Set
35	Drill twist straight shank 8 mm to 15 mm by 1/2 mm	1 Set
36	Taps and dies complete set in box B.A	1 no.
37	Taps and dies complete set in box with-worth.	1 no.

38	Taps and dies complete set in box 3-18 mm set of 10	1 no.
39	File warding 15 cm smooth	4 nos.
40	File knife edge 15 cm smooth	4 nos.
40	File cut saw 15 cm smooth	4 nos.
41	File feather edge 15 cm smooth	4 nos.
43	File triangular 15 cm smooth	2 nos.
44	File round 20 cm second cut	8 nos.
45	File square 15 cm second cut	4 nos.
46	File square 25 cm second cut	4 nos.
47	Feeler gauge 10 blades	1 set
48	File triangular 20 cm second cut.	8 nos.
49	File flat 30 cm second cut.	8 nos.
50	File flat 20 cm bastard	8 nos.
51	File flat 30 cm bastard.	8 nos.
52	File Swiss type needle set of 12.	2 sets
53	File half round 25 cm second cut.	8 nos.
54	File half round 25 cm bastard.	4 nos.
55	File round 30 cm bastard.	4 nos.
56	File hand 15 cm second cut.	8 nos.
57	Card file.	8 nos.
58	Oil Stone 15 cm x 5 cm x 2.5 cm	4 nos.
59	Stone carborandum 15 cm x 5 cm x 5 cm x 4 cm.	2 nos.
60	Oil Can 0.25 liters.	2 nos.
61	Pliers combination 15 cm	2 nos.
62	Soldering Iron 350 gm.	2 nos.
63	Blow Lamp 0.50 liters.	2 nos.
64	Spanner D.E. 6 -26 mm set of 10 pcs.	8 nos.
65	Spanner adjustable 15 cm	2 nos.
66	Interchangeable ratchet socket set with a 12 mm driver, sized10-32 mm set of 18 socket & attachments.	1 set
67		
68	Glass magnifying 7 cm	1 set 2 nos.
<u> </u>	Clamp toolmaker 5 cm and 7.5 cm set of 2.	2 nos.
70	Clamp "C" 5 cm	2 nos.
70	Clamp "C" 10 cm	2 nos.
71	Hand Reamer adjustable cover max 9,12,18mm – set of 3	1 set
73	Hand Reamer taper 4 -9mm set of 6 OR 4 -7 mm set of 4.	1 set
73	Reamer parallel 12 - 16mm set of 5.	1 set 1 no.
74	Scraper flat 15 cm.	
76	*	8 nos.
70	Scraper triangular 15 cm 8 nos.	
	Scraper half round 15cm 8 nos.	
78	Chisel cold 9 mm cross cut 9 mm diamond. 8 each	
79	Chisel cold 19 mm flat	8 nos.
80	Chisel cold 9 mm round noze.	8 nos.
81	Stud Extractor EZY – out	2 nos.
82	Combination Set 30 cm.	2 nos.

83	Micrometer $0 - 25$ mm outside.	3 nos.
84	Micrometer 25 – 50 mm outside.	3 nos.
85	Micrometer 50 –75 mm outside.	2 nos.
86	Micrometer inside 25 - 50 mm with extension rods.	1 no.
87	Vernier caliper 15 cm	1 no.
88	Vernier height gauges 30 cm.	1 no.
89	Vernier bevel protractor.	1 no.
90	Screw pitch gauge.	1 no.
91	Wire gauge, metric standard.	1 no.
92	Drill twist Taper Shank 12 mm to 25 mm x 1.5.	1 no.
93	Drill chuck 12 mm.	1 no.
94	Pipe wrench 40 cm	1 no.
95	Pipe vice 100mm	1 no.
96	Adjustable pipe tap set BSP with die set cover pipe size 15, 20, 25,32,38,50 mm.	1 no.
97	Wheel dresser (One for 4 units).	1 no.
98	Machine vice 10 cm.	1 no.
99	Machine vice 15 cm	1 no.
100	Sleeve drill Morse 0 - 1, 1 - 2, 2 - 3.	1 Set
101	Vice bench 12 cm jaws.	16 nos.
102	Vice leg 10 cm jaw.	2 nos.
103	Bench working 240 x 120 x 90 cm.	4 nos.
104	Almirah 180 x 90 x 45 cm.	2 nos.
105	Lockers with 6 drawers (standard size).	2 nos.
106	Metal rack 182 x 182 x 45 cm	1 no.
107	Instructor Table	1 no.
108	Instructor Chair	1 no.
109	Black board with easel.	1 no.
110	Fire extinguisher (For 4 Units)	2 nos.
111	Fire buckets.	2 nos.
112	Machine vice 100mm.	2 nos.
113	Wing compass 25.4 cm or 30 cm.	2 nos.
114	Hand hammer 1 kg. with handle.	2 nos.

Sl. No.	Name of the items	Qty
115	Hammer smith 2 kg. With handle.	2 nos.
116	Tongs roving 350mm.	2 nos.
117	Tongs fiat 350mm.	2 nos.
118	Smith's square 45 cm x 30 cm.	1 no.
119	Cold set rodded 25X200mm.	2 nos.
120	Hot set rodded 25X200mm.	1 no.
121	Swages top & bottom 12 mm /19	1 Each
122	Swage block 35 x 35 x 12 cm.	1 no.
123	Flatters (rodded) 55 mm square.	2 nos.
124	Fuller top & bottom 6 mm 9 mm (Pair).	2 nos.
125	Anvil 50 kg.	2 nos.
126	Anvil stand	2 nos.
127	Shovel.	2 nos.
128	Trammel 30cm.	1 no.
129	Rake.	2 nos.
130	Quenching tank (To be made in the Institute).	1 no.
131	Pocker.	2 nos.
132	Hardle.	2 nos.
133	Leather apron.	2 nos.
134	Prick punch	2 nos.
135	Mallet.	2 nos.
136	Snips straight 25 cm.	2 nos.
137	Setting hammers with handle.	2 nos.
138	Planishing hammer.	2 nos.
139	Snip bent 25 cm.	2 nos.
140	Stake hatchet.	2 nos.
141	Stake grooving.	2 nos.
142	Gauge imperial sheet.	1 no.

C: Tools for Allied Trade- Blacksmith & Sheet Metal Work

The specifications of the items in the above list have been given in Metric Units. The items which are available in the market nearest of the specification as mentioned above, if not available as prescribed should be procured Measuring instruments such as steel rule which are graduated both English and Metric Units may be procured, if available.

Sl.No.	Name of the Tools & Equipment	Quantity
*1.	Slip Gauge as Johnson metric set.	1 Set
2.	Carbide Wear Block 1 mm – 2 mm.	2 each
*3.	Gauge snap Go and Not Go 25 to 50 mm by 5mm. Set of 6 pcs.	1 Set
*4.	Gauge plug single 3 ended 5 to 55 by 5 mm. Set of 11 pcs.	1 Set
**5.	Gauge telescopic upto 150 mm.	1 no.
6.	Dial test indicator .01 mm on stand	1 no.
7.	Sine bar 125 mm.	1 no.
8.	Sine bar 250 mm.	1 no.
9.	Lathe tools H.S.S. tipped set.	2 nos.
10.	Lathe tools bit 6 mm x 75 mm.	4 nos.
11.	Lathe tools bit 8 mm x 75 mm.	4 nos.
12.	Lathe tools bit 10 mm x 85mm.	4 nos.
13.	Arm strong type tool bit holder R.H.	2 nos.
14.	Arm strong type tool bit holder L.H.	2 nos.
15.	Arm strong type tool bit holder straight.	2 nos.
16.	Stilson wrenches 25 cm	2 nos.
17.	Pipe cutter 6 mm to 50 mm wheel type.	1 no.
18.	Pipe bender spool type up to 25 mm. with stand manually operated.	1 no.
19.	Adjustable pipe chain tonge to take pipes up to 300 mm.	1 no.
20.	Adjustable spanner 38 cm long.	1 no.
**21.	Dial vernier caliper 0 – 200 mm LCO 0.05 mm. (Universal type).	1 no.
**22.	Screw thread micrometer with interchangeable 0-25mm. Pitch anvils for checking metric threads 60.	1 no.
23.	Depth micrometer 0-25 mm. 0.01 mm.	1 no.
**24.	Vernier caliper 0-150 mm. L.C. 0.02 mm.	1 no.
**25.	Comparators stand with dial indicator LC 0.01mm.	1 no.
26.	Engineer's try square (knife-wedge) 150 mm blade.	1 no.
**27	Surface roughness comparison plates N1-N12 grade	1 Set

D : Modified list of tools for the 3rd and 4th semester for fitter trade.

E: General Machinery Installations –

Sl. No.	Name & Description of Machines	Quantity
*1.	Lathe all geared head stock S.S. and S.C. height of centre over bed 15 cm – gap head complete with accessories e.g. pump, all fittings and splash guard driving plate with drives, face plate 3 jaw and 4 jaw chucks fixed and travelling steady compound turret tool post, taper turning attachment, fixed and running centres, driving dogs straight and bent tails.	2 Nos.
2	Drilling machine pillar sensitive 0-20 mm cap with swivel table motorised with chuck & key.	1 no.
3	Drilling machine bench sensitive 0-12 mm cap motorised with chuck and key.	2 nos.

4	Forge portable hand blower 38 cm to 45 cm.	1 no.
5	Grinding machine (General purpose) D.E. pedestal with 2 cm. dia wheels rough and	1 no.
	smooth with twist drill grinding attachment.	

Note:- (*) No additional number of items are required to be provided up to four batches of trainees i.e. two batches in the first shift and two in the second shift.

(**) Only one number need be provided in each I.T.I. irrespective of No. of Units.

F: List of additional tools for allied trade in welding

Sl. No.	Name & Description of Machines	Quantity
1.	Transformer welding set 150 amps. – continuous welding current, with all accessories and electrode holder	1 Set
2.	Welder cable to carry 200 amps. With flexible rubber cover	20 Meter
3.	Lungs for cable	12 Nos.
4.	Earth clamps.	2 Nos.
5.	Arc welding table (all metal top) 122 cm X 12 cm X 60 cm with positioner.	1 No.
6.	Oxy – acetylene gas welding set equipment with hoses, regulator and other accessories.	1 Set.
7.	Gas welding table with positioner	1 No
8.	Welding torch tips of different sizes	1 Set
9.	Gas lighter.	2 Nos
10.	Trolley for gas cylinders.	1 No
11.	Chipping hammer.	2 Nos
12.	Gloves (Leather)	2 Pairs
13.	Leather apron.	2 Nos
14.	Spindle key for cylinder valve.	2 Nos.
15.	Welding torches 5 to 10 nozzles.	1 Set.
16	Welding goggles	4 Pairs.
17.	Welding helmet with coloured glass	2 Nos.
18.	Tip cleaner	10 Sets.

<u>Note: -</u> Those additional items are to be provided for the Allied Trade Training where the welding trade does not exist.

LIST OF ISI BOOKS FOR REFERENCE FOR FITTER TRADE		
(For use of Instructors only)		

SL.No.	Titles	Code
1.	Spring calipers.	IS : 4052 – 1967
2.	Punches	IS: 413-1974
3.	Matric steel scales for Engineers.	IS : 1481 - 1970
4.	Engineers square.	IS: 2013 – 1972
5.	V-Block.	IS: 2049 – 1974
6.	Steel straight edges.	IS: 2220 – 1962
7.	Hacksaw blades.	IS : 2504 - 1977
8.	Bench vices.	IS : 2586 - 1975
9.	Chisels (Cold)	IS: 402 - 1974
10.	Engineer's file.	IS : 1931 - 1972
11.	Surface plates (C.I.)	IS: 2285 – 1974
12.	Twist drill	IS : 5100 – 1960 to 5106
13.	Vernier depth gauges.	IS: 4213 – 1967
14.	External micrometers.	IS: 2967 – 1964
15.	A dimension for counter – sinks & counter bores.	IS: 3406 – 1975
16.	Internal micrometers.	IS: 2966 – 1964
17.	Vernier calipers.	IS: 3651 – 1974
18.	Vernier height gauges.	IS: 2021 – 1964
19.	Gib – head keys and key ways.	IS: 2203 – 1974
20.	Taper keys and key ways.	IS: 2292 – 1974
21.	Screw driver.	IS: 884-1972
22.	Bevel protractors.	IS: 4229 – 1970
23.	Reamers.	IS: 1836 – 1961
24.	Thread cutting dies.	IS: 1859 – 1961
25.	Metric screw threads (Metric thread pitch-gauges)	IS: 4211 – 1967
26.	Dial gauges.	IS: 2092 – 1962
27.	Hexagonal bolts and nuts.	IS: 2038-1968
28.	Feeler gauges (m.m. ranges).	IS: 3179 – 1976
29.	Spanners, open jaw.	IS: 2028 – 1968
30.	Thickness of sheet & diameters of wire	IS: 1137 – 1950
31.	Centre drills.	IS: 6703 – 1977
32.	Lathe, sizes for general purpose.	IS: 2392 – 1963
33.	Recommendations for tapping drill sizes.	IS: 3230 – 1970
34.	Needle files.	IS : 3152 – 1965
35.	Plain plug gauges.	IS : 6137 – 1871
36.	Plain ring gauges (Go)	IS: 3435 – 1972
37.	Snap gauges (Go & No Go)	IS: 3477 – 1973
38.	Slip gauges.	IS : 2984 – 1966
39.	Ball & roller Bearings gauging practice for.	IS: 4025 – 1967
40.	V-belt for Industrial purposes.	IS : 2404 – 1974
41.	Limits & fits for engineering, recommendations for	IS: 919 – 1963
42.	Plain limit gauges tolerances for.	IS: 3455 – 1971
43.	Rivets for general purposes.	IS : 2155 – 1961
44.	Tapers for general engineering purposes.	IS: 3458 – 1966
45.	General Engineering drawing.	IS: 696 – 1971